

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

1186  
NNE  
> 1  
1.561 mi.  
8244 ft.

**BENSONHURST SUBSTATION**  
**2074 MCDONALD AVE**  
**BROOKLYN, NY**

**NY Spills** **S107415851**  
**N/A**

**Relative:**  
**Higher**

**Actual:**  
**22 ft.**

**SPILLS:**

Name: BENSONHURST SUBSTATION  
Address: 2074 MCDONALD AVE  
City,State,Zip: BROOKLYN, NY  
Spill Number/Closed Date: 0508184 / 2005-11-30  
Facility ID: 0508184  
Facility Type: ER  
DER Facility ID: 301133  
Site ID: 353724  
DEC Region: 2  
Spill Cause: Equipment Failure  
Spill Class: C4  
SWIS: 2401  
Spill Date: 2005-10-08  
Investigator: GDBREEN  
Referred To: Not reported  
Reported to Dept: 2005-10-08  
CID: 71  
Water Affected: Not reported  
Spill Source: Commercial/Industrial  
Spill Notifier: Responsible Party  
Cleanup Ceased: Not reported  
Cleanup Meets Std: False  
Last Inspection: Not reported  
Recommended Penalty: False  
UST Trust: False  
Remediation Phase: 0  
Date Entered In Computer: 2005-10-09  
Spill Record Last Update: 2005-11-30  
Spiller Name: ERT DESK  
Spiller Company: CON EDISON  
Spiller Address: 4 IRVING PLACE  
Spiller Company: 001  
Contact Name: ERT DESK'  
DEC Memo: "161444. 10/8/05 - 2350hrs - Augusto Chicas # 85629 Sr. S/S Operator, Central Stations, reports a can in Cap Bank # 5 was on fire, which was extinguished by Chicas with a fire extinguisher, and spilled 2 oz non pcb oil from Cap Bank onto bluestone. No sewers or waterways affected. No private property affected. Substance owned by Coned. No sampling necessary. CIG Tom Enright notified by S.Supv Pat Abel @ 2123hrs ERT A. Natale notified @ 2130hrs. A. Natale is on location.

Remarks: A. Natale reports spill is contained and cleanup is scheduled for 10/09/05 day shift. cn#19661 Closed. 11-30-05. see eDocs. GB "  
"CAN CAUGHT FIRE. POSSIBILITY OF OIL DRIPPING ONTO BLUE STONE. CURRENTLY UNDER INVESTIGATION. 161444."

**All Materials:**

Site ID: 353724  
Operable Unit ID: 1111173  
Operable Unit: 01  
Material ID: 2101216  
Material Code: 0066A  
Material Name: unknown petroleum  
Case No.: Not reported

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

Material FA:	Petroleum
Quantity:	5.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported